



## M1 West Meadow Viaduct and Diseworth Long Whatton Bridge




Non-motorway traffic diversion from Finger Farm roundabout follow A453 westbound, turn left onto Moor Lane signposted A453 (A42). Continue over A42 and at roundabout take 3rd exit to join A42 Westbound.



Slip Road Closure - Slip road from A453 at East Midlands Airport onto M1 and A42 at Junction 23A will be closed.



A42 slip diversion - to get onto A42 from the A453 at East Midlands airport Junction 23A follow A453 North until Junction 24. Join M1 Southbound here and then follow the signage through Junction 23a and onto the A42 West-



M1 SB diversion at Junction 23A follow signed diversion to A42 Westbound and onto M42, continue through Junction 9 to Junction 7A and follow signs for M6 Southbound joining the M6 at Junction 3A. Continue Southbound on M6 until the junction with M1. Follow signage for M1 Southbound and re-join at Junction 19.